Hi! I am Freddy the Forklift Fixer.

This is me when I'm pleased.



This is me when I'm concerned.



Right now, I am concerned about replacing the <u>worn out risers</u> under my Crown PE3000 because the bearings burnt out from shrink wrap around the wheels:



A BIG problem in warehouses with shrink wrapped packaging!

Fortunately, available now:





A low priced \$395 riser assembly with bearing saver wheels from Hettinger) fits the bill.

My grimace



Turns to a grin!

This is me happy to stay within budget and get better utilization from my Crown PE3000 palette jack!



David M. Sherr is a founder of **Supply Chain Analytics™** and an associate of **Hettinger, Inc.**